
MAR 0 5 2004 THE THATEIN


SERIAL NO.: 10/714,810
INVENTOR: EREL ET AL.
TITLE: "ELEVATED SUPPORT POLE WITH AUTOMATIC ELECTRICAL CONNECTION AND DISCONNECTION"

ATTY: BRADLEY K. GROFF ATTY TEL: 770.984.2300 ATTY DOCKET NO.: 2V02.1-022



SERIAL NO.: 10/714,810
INVENTOR: EREL ET AL.
TITLE: "ELEVATED SUPPORT POLE WITH AUTOMATIC
ELECTRICAL CONNECTION AND DISCONNECTION"

ATTY: BRADLEY K. GROFF
ATTY TEL: 770.984.2300
ATTY DOCKET No.: 2V02.1-022
2/16



SERIAL NO.: 10/714,810
INVENTOR: EREL ET AL.
TITLE: "ELEVATED SUPPORT POLE WITH AUTOMATIC ELECTRICAL CONNECTION AND DISCONNECTION"

ATTY: BRADLEY K. GROFF
ATTY TEL: 770.984.2300
ATTY DOCKET NO.: 2V02.1-022
3/16




Fig. 3

SERIAL NO.: 10/714,810
INVENTOR: EREL ET AL.
TITLE: "ELEVATED SUPPORT POLE WITH AUTOMATIC
ELECTRICAL CONNECTION AND DISCONNECTION"

ATTY: BRADLEY K. GROFF ATTY TEL: 770.984.2300 ATTY DOCKET NO.: 2V02.1-022 4/16





Fig. 4

SERIAL NO.: 10/714,810
INVENTOR: EREL ET AL.
TITLE: "ELEVATED SUPPORT POLE WITH AUTOMATIC ELECTRICAL CONNECTION AND DISCONNECTION"

ATTY: BRADLEY K. GROFF
ATTY TEL: 770.984.2300
ATTY DOCKET NO.: 2V02.1-022
5/16






Fig. 5b

SERIAL No.: 10/714,810 INVENTOR: EREL ET AL. INVENTOR: EREL ET AL.

TITLE: "ELEVATED SUPPORT POLE WITH AUTOMATIC
ELECTRICAL CONNECTION AND DISCONNECTION"
ATTY: BRADLEY K. GROFF
ATTY TEL: 770.984.2300
ATTY DOCKET NO.: 2V02.1-022
6/16





Fig. ba



SERIAL NO.: 10/714,810
INVENTOR: EREL ET AL.

TITLE: "ELEVATED SUPPORT POLE WITH AUTOMATIC ELECTRICAL CONNECTION AND DISCONNECTION"

ATTY: BRADLEY K. GROFF

ATTY TEL: 770.984.2300

ATTY DOCKET NO.: 2V02.1-022

7/16




Fig. 7

SERIAL NO.: 10/714,810
INVENTOR: EREL ET AL.

TITLE: "ELEVATED SUPPORT POLE WITH AUTOMATIC ELECTRICAL CONNECTION AND DISCONNECTION"

ATTY: BRADLEY K. GROFF

ATTY TEL: 770.984.2300

ATTY DOCKET NO.: 2V02.1-022

8/16




Fig. A

SERIAL NO.: 10/714,810
INVENTOR: EREL ET AL.
TITLE: "ELEVATED SUPPORT POLE WITH AUTOMATIC
ELECTRICAL CONNECTION AND DISCONNECTION"
ATTY: BRADLEY K. GROFF

ATTY: BRADLEY K. GROFF ATTY TEL: 770.984.2300 ATTY DOCKET NO.: 2V02.1-022 9/16





Fig. 9

SERIAL NO.: 10/714,810
INVENTOR: EREL ET AL.
TITLE: "ELEVATED SUPPORT POLE WITH AUTOMATIC
ELECTRICAL CONNECTION AND DISCONNECTION"
ATTY: BRADLEY K. GROFF
ATTY TEL: 770.984.2300

ATTY TEL: 770.984.2300
ATTY DOCKET NO.: 2V02.1-022



Remote Control Panel

Fig. 1//

SERIAL NO.: 10/714,810
INVENTOR: EREL ET AL.


TITLE: "ELEVATED SUPPORT POLE WITH AUTOMATIC ELECTRICAL CONNECTION AND DISCONNECTION"

ATTY: BRADLEY K. GROFF

ATTY TEL: 770.984.2300

ATTY DOCKET NO.: 2V02.1-022

11/16



SERIAL NO.: 10/714,810
INVENTOR: EREL ET AL.
TITLE: "ELEVATED SUPPORT POLE WITH AUTOMATIC
ELECTRICAL CONNECTION AND DISCONNECTION"

ATTY: BRADLEY K. GROFF
ATTY TEL: 770.984.2300
ATTY DOCKET NO.: 2V02.1-022
12/16





Fig. 13

SERIAL NO.: 10/714,810
INVENTOR: EREL ET AL.

TITLE: "ELEVATED SUPPORT POLE WITH AUTOMATIC ELECTRICAL CONNECTION AND DISCONNECTION"
ATTY: BRADLEY K. GROFF
ATTY TEL: 770.984.2300
ATTY DOCKET NO.: 2V02.1-022
13/16



SERIAL NO.: 10/714,810
INVENTOR: EREL ET AL.
TITLE: "ELEVATED SUPPORT POLE WITH AUTOMATIC ELECTRICAL CONNECTION AND DISCONNECTION"

ATTY: BRADLEY K. GROFF ATTY TEL: 770.984.2300 ATTY DOCKET NO.: 2V02.1-022 14/16




Fig. 15

SERIAL NO.: 10/714,810
INVENTOR: EREL ET AL.
TITLE: "ELEVATED SUPPORT POLE WITH AUTOMATIC
ELECTRICAL CONNECTION AND DISCONNECTION"
ATTY: BRADLEY K. GROFF

ATTY: BRADLEY N. GROFF ATTY TEL: 770.984.2300 ATTY DOCKET NO.: 2V02.1-022 15/16




Fig. 16

SERIAL NO.: 10/714,810
INVENTOR: EREL ET AL.
TITLE: "ELEVATED SUPPORT POLE WITH AUTOMATIC ELECTRICAL CONNECTION AND DISCONNECTION" ATTY: BRADLEY K. GROFF

ATTY TEL: 770.984.2300
ATTY DOCKET NO.: 2V02.1-022

